Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

LOCATION: COUNTY:

DISTRICT:

41049

SEDO

American Energy Corp Century Mine 43521 Mayhugh Hill Rd Twp Hwy 88 Beallsville, OH 43716

PERMIT NUMBER: STATION CODE: MONITORING PERIOD: REPORTING LAB: Original

0IL00091*GD 601 **2009-01-01** To: **2009-01-31**

STATUS:

ANALYST: NO DISCHARGE INDICATOR: AL

PARAMETER	Nitrogen, Ammonia (NH3)	CBOD 5 day					
PARAMETER CODE	00610	80082					
UNITS	4106	4106					
FREQUENCY SAMPLING TYPE	1 / 2 Weeks Grab	1 / 2 Weeks Grab		- 			
2009-01-01		3.00					
2009-01-02		·					
2009-01-03							
2009-01-04							
2009-01-05							
2009-01-06							
2009-01-07							-
2009-01-08							
2009-01-09							
2009-01-10							
2009-01-11							
2009-01-12							
2009-01-13							
2009-01-14							
2009-01-15							
2009-01-16							
2009-01-17							
2009-01-18							
2009-01-19							
2009-01-20				<u> </u>			
2009-01-21	<u> </u>	T-12	<u> </u>				
2009-01-22	<u> </u>		<u> </u>				
2009-01-23							
2009-01-24		·		<u> </u>			
2009-01-25							
2009-01-26	<u> </u>				·		
2009-01-27				<u></u>			
2009-01-28	<u> </u>		<u></u>	<u> </u>			
2009-01-29	<u> </u>			<u> </u>			
2009-01-30	ļ						
2009-01-31	<u> </u>			<u> </u>			
Minimum	{					-{	
Maximum Average				-		╼╂╼╼╼═╬	
Count	<u> </u>					 _	
Name of Responsible Officion Authorized Representation		ubmitted herein and b	e personally examined at based on my inquiry of the	hose	Signature of Respons Repr	ible Official or Authorized esentative	Submission Date/Tim
Dennis Dubiel	submitted information significant penaltics for	individuals immediately responsible for obtaining the information, I believe the submitted information is true, accurate and complete. I am aware that there are significant penalties for submitting false information, including the possibility of line and imprisonment.					